




Part # 11059571 - 1961-1962 GM B-Body Steering Kit

Recommended Tools



Major ComponentsIn the box

QTY	Part Number	Description
2	90000091	Tie Rod Adjuster
2	99800002	5/8"-18 Right Hand Jam Nut
2	99800003	5/8"-18 Left Hand Jam Nut
2	90003053	Inner Tie Rod - 10.750" Long(from grease zerk) - 5/8"-18 Right Hand Thread
2	90003046	Outer Tie Rod - 3.500" Long(from grease zerk) - 5/8"-18 Left Hand Thread
1	90003043	Idler Arm

NOTES:

This Tie Rod Adjuster is designed to take place of the OEM steel sleeve.

One end of the adjuster has a **groove** cut in it, this is the **LEFT HAND** threaded side.

When installing the Tie Rod Adjuster, use antisieze compound on the threads.

USE THE SIGHT HOLES IN THE SIDE OF THE TIE ROD ADJUSTER TO ENSURE PROPER THREAD ENGAGEMENT.

