

INSTRUCTIONS


910-65050



3 3/8" Speedometer, Mechanical Installation Instructions

MOUNTING

1. Mount the meter in a 3 3/8 dia. Hole (make sure that hole is not cut too large)
2. Secure the speedometer to the dashboard using provided bracket and hardware as shown (cable and grommet are not provided)




LIGHT CONNECTION

Install light in back of speedometer and connect one wire to 12 V dash lighting circuit, connect other to negative ground

CABLE CONNECTION

1. Connect it to the cable input on back of speedometer if the existing cable is being used
2. If a new cable is needed, purchase a customer-made cable from a local source. The cable input on back of speedometer accepts only 0.104 SQ male drive, make sure connections fit properly before tightening or speedometer may be damaged



NOTE

1. The meter is set up for a 1:1 ratio (60 MPH at 1000 input to meter head), if vehicle tire size is not stock (original), a different driven gear in the transmission may be required for speed accuracy
2. The rotation of the input cable should be in the same direction of the pointer movement, which is clockwise

Speedway Motors Inc.,
P. O. Box 81906 Lincoln, NE 68501
402-323-3200 www.SpeedwayMotors.com

